

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND 550 BACKHOE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 4 Wire Condenser Motor Blower Wheel, 3/8" Bore, 4 1/4" OD x 5 7/8" Offset Hub Blower Wheel, 3/8" Bore, 4 1/4" OD x 5 7/8" Offset Hub	E2NN18456AA	7231FHD
	E3NN19C634AA	BM-0368
	N/A	03045
	N/A	03046
<b>Clutch</b> -York, 6" Dia., 2 Groove, Standard Duty York, 6" Dia., 2 Groove, Heavy Duty	86529809	75R0452
	86529809	75R1202
<b>Compressor Shaft Seal Kit</b> -Tecumseh York	C9AZ19655B	20836
	C9AZ19655B	20986
<b>Compressor</b> -York, LH Suction, Rotolok York, RH Suction, Rotolok	N/A	7044
	N/A	7054
<b>Switch</b> -Thermostat Thermo Disc	D8NN19A945AA	26303
	D6NN19N584A	71R6300
<b>FORD/NEW HOLLAND 555 BACKHOE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 4 Wire Condenser Motor Blower Wheel, 3/8" Bore, 4 1/4" OD x 5 7/8" Offset Hub Blower Wheel, 3/8" Bore, 4 1/4" OD x 5 7/8" Offset Hub	E2NN18456AA	7231FHD
	E3NN19C634AA	BM-0368
	N/A	03045
	N/A	03046
<b>Clutch</b> -York, 6" Dia., 2 Groove, Standard Duty York, 6" Dia., 2 Groove, Heavy Duty	86529809	75R0452
	86529809	75R1202
<b>Compressor Shaft Seal Kit</b> -Tecumseh York	C9AZ19655B	20836
	C9AZ19655B	20986
<b>Compressor</b> -York, LH Suction, Rotolok York, RH Suction, Rotolok	N/A	7044
	N/A	7054
<b>Expansion Valve</b> -O'Ring	E3NN19849AA	38877
<b>Switch</b> -Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND 555A BACKHOE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 4 Wire Condenser Motor Blower Wheel, 3/8" Bore, 4 1/4" OD x 5 7/8" Offset Hub Blower Wheel, 3/8" Bore, 4 1/4" OD x 5 7/8" Offset Hub	E2NN18456AA	7231FHD
	E3NN19C634AA	BM-0368
	N/A	03045
	N/A	03046
<b>Clutch</b> -York, 6" Dia., 2 Groove, Standard Duty York, 6" Dia., 2 Groove, Heavy Duty	86529809	75R0452
	86529809	75R1202
<b>Compressor Shaft Seal Kit</b> -Tecumseh York	C9AZ19655B	20836
	C9AZ19655B	20986
<b>Compressor</b> -York, LH Suction, Rotolok York, RH Suction, Rotolok	N/A	7044
	N/A	7054
<b>Expansion Valve</b> -O'Ring	E3NN19849AA	38877
<b>Switch</b> -Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND 555B BACKHOE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 4 Wire Condenser Motor Blower Wheel, 3/8" Bore, 4 1/4" OD x 5 7/8" Offset Hub Blower Wheel, 3/8" Bore, 4 1/4" OD x 5 7/8" Offset Hub	E2NN18456AA	7231FHD
	E3NN19C634AA	BM-0368
	N/A	03045
	N/A	03046

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND 555B BACKHOE Cont.</b>		
<b>Clutch</b> -York, 6" Dia., 2 Groove, Standard Duty York, 6" Dia., 2 Groove, Heavy Duty	86529809	75R0452
	86529809	75R1202
<b>Compressor Shaft Seal Kit</b> -Tecumseh York	C9AZ19655B	20836
	C9AZ19655B	20986
<b>Compressor</b> -York, LH Suction, Rotolok York, RH Suction, Rotolok	N/A	7044
	N/A	7054
<b>Expansion Valve</b>	E3NN19849AA	38877
<b>Switch</b> -Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND 555D BACKHOE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Resistor, 3 Terminal  Resistor, 4 Terminal  Blower Motor Assembly	86010530	04437
	1255876C1 700710564	03242
	E5NN18N350AA E5NN18B310AA	03246
	E7NN18456AC	BA4011
<b>Clutch Bearing</b> -Sanden SD510	F0NN19D666AA	52560
<b>Clutch</b> -New Sanden SD510	F0NN19D649BA	8297
<b>Compressor Shaft Seal</b> -Sanden SD510	F0NN19655AA	52552
<b>Compressor</b> -New Sanden SD510 New Sanden SD7H15, 5/01/1994 and Newer	F0NN19D629BA	9125AM
	85702706, 86511121	4673
<b>Expansion Valve</b> -Block Type	F1NN19849AA	EX03700
<b>Receiver Drier</b>	F1NN19959AA	21723
<b>Switch</b> -Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND 555E BACKHOE</b>		
<b>Blower Motor</b> -Assembly Resistor	85813079	73R5552
	85804041	03255
<b>Clutch Bearing</b> -Sanden SD7H15	85817172	52565
<b>Clutch</b> -New Sanden SD7H15	85817171	8445
<b>Compressor Shaft Seal Kit</b>	85817173	52554
<b>Compressor</b> -New Sanden SD7B10, Serial No. 31018060 and Below New Sanden SD7H15, Serial No. 31018061 and Above	85804059	7170AM
	85812045	C009610
<b>Condenser</b> -Serial No. 31018061 and Above	85812052	AC003345
<b>Expansion Valve</b> -Block Type	85804037	38892
<b>Receiver Drier</b> -Serial No. 31011330 and Below * Also needs 461-3126 Serial No. 31018061 and Above Condenser Mount, Serial No. 31018061 & Above	85804063	RD-3661*
	85812095	74R2536
	85812053	RD00179
<b>Switch</b> -Blower On/Off A/C High/Low Pressure, Drier Mount	9966238	04455
	518486	04456
	85804065	04525

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND 575D BACKHOE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 2 Wire Resistor, 3 Terminal  Resistor, 4 Terminal  Blower Motor Assembly	86010530	04437
	1255876C1 700710564	03242
	E5NN18N350AA E5NN18B310AA	03246
	E7NN18456AC	BA4011
<b>Clutch Bearing</b> -Sanden SD510	F0NN19D666AA	52560
<b>Clutch</b> -New Sanden SD510	F0NN19D649BA	8297
<b>Compressor Shaft Seal Kit</b> -Sanden SD510	F0NN19655AA	52552
<b>Compressor</b> -New Sanden SD510 New Sanden SD7H15, 5/01/1994 and Newer	F0NN19D629BA	9125AM
	85702706, 86511121	4673
<b>Expansion Valve</b> -Block Type	F1NN19849AA	EX03700
<b>Receiver Drier</b>	F1NN19959AA	21723
<b>Switch</b> -Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND 575E BACKHOE</b>		
<b>Blower Motor</b> -Assembly Resistor	85813079	73R5552
	85804041	03255
<b>Clutch Bearing</b> -Sanden SD7H15	85817172	52565
<b>Clutch</b> -New Sanden SD7H15	85817171	8445
<b>Compressor Shaft Seal Kit</b>	85817173	52554
<b>Compressor</b> -New Sanden SD7H15	85812045	C009610
<b>Condenser</b> -Serial No. 31018061 and Above	85812052	AC003345
<b>Expansion Valve</b> -Block Type	85804037	38892
<b>Receiver Drier</b> -Serial No. 31011330 and Below * Also needs 461-3126 Serial No. 31018061 and Above Condenser Mount, Serial No. 31018061 & Above	85804063	RD-3661*
	85812095	74R2536
	85812053	RD00179
<b>Switch</b> -Blower On/Off A/C High/Low Pressure, Drier Mount	9966238	04455
	518486	04456
	85804065	04525
<b>FORD/NEW HOLLAND 655 BACKHOE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 4 Wire Condenser Motor Blower Motor Assembly	E2NN18456AA	7231FHD
	E3NN19C634AA	BM-0368
	E2NN18456AA	BA4080
<b>Clutch</b> -York, 6" Dia., 2 Groove, Standard Duty York, 6" Dia., 2 Groove, Heavy Duty	86529809	75R0452
	86529809	75R1202
<b>Compressor Shaft Seal Kit</b> -Tecumseh York	C9AZ19655B	20836
	C9AZ19655B	20986
<b>Compressor</b> -York, LH Suction, Rotolok York, RH Suction, Rotolok	N/A	7044
	N/A	7054
<b>Expansion Valve</b>	E3NN19849AA	38877
<b>Switch</b> -Blower	E9NN15122AA	71R1150

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND 655A BACKHOE</b>		
<b>Blower Motor</b> -3/8" Double Shaft, 4 Wire Condenser Motor Blower Motor Assembly	E2NN18456AA	7231FHD
	E3NN19C634AA	BM-0368
	E2NN18456AA	BA4080
<b>Clutch</b> -York, 6" Dia., 2 Groove, Standard Duty York, 6" Dia., 2 Groove, Heavy Duty	86529809	75R0452
	86529809	75R1202
<b>Compressor Shaft Seal Kit</b> -Tecumseh York	C9AZ19655B	20836
	C9AZ19655B	20986
<b>Compressor</b> -York, LH Suction, Rotolok York, RH Suction, Rotolok	N/A	7044
	N/A	7054
<b>Expansion Valve</b>	E3NN19849AA	38877
<b>Switch</b> -Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND 655C BACKHOE</b>		
<b>Blower Motor</b> Resistor, 3 Terminal  Resistor, 4 Terminal Blower Motor Assembly	86010530	04437
	1255876C1 700710564	03242
	E5NN18N350AA	03246
	E7NN18456AC	BA4011
<b>Compressor</b> -New Sanden SD510  New Sanden SD7H15SHD	F0NN19D629BA 9704118, 450805	9125AM
	85702706, 86511121	4673
<b>Expansion Valve</b> -Block Type	F1NN19849AA	EX03700
<b>Receiver Drier</b>	F1NN19959AA	21723
<b>Switch</b> -Blower	E9NN15122AA	71R1150
<b>FORD 655D BACKHOE</b>		
<b>Blower Motor</b> Resistor, 3 Terminal  Resistor, 4 Terminal Blower Motor Assembly	86010530	04437
	1255876C1 700710564	03242
	E5NN18N350AA E5NN18B310AA	03246
	E7NN18456AC	BA4011
<b>Clutch Bearing</b> -Sanden SD510	F0NN19D666AA	52560
<b>Clutch</b> -New Sanden SD510	F0NN19D649BA	8297
<b>Compressor Shaft Seal Kit</b> -Sanden SD510	F0NN19655AA	52552
<b>Compressor</b> -New Sanden SD510 New Sanden SD7H15, 5/01/1994 and Newer	F0NN19D629BA	9125AM
	85702706, 86511121	4673
<b>Expansion Valve</b> -Block Type	F1NN19849AA	EX03700
<b>Receiver Drier</b>	F1NN19959AA	21723
<b>Switch</b> -Blower	E9NN15122AA	71R1150

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND 655E BACKHOE</b>		
Blower Motor-Assembly Resistor	85813079	73R5552
	85804041	03255
Clutch Bearing-Sanden SD7H15	85817172	52565
Clutch-New Sanden SD7H15	85817171	8445
Compressor Shaft Seal Kit	85817173	52554
Compressor-New Sanden SD7H15	85812045	C009610
Condenser-Serial No. 31018061 and Above	85812052	AC003345
Expansion Valve-Block Type	85804037	38892
Receiver Drier-Serial No. 31011330 and Below * Also needs 461-3126 Serial No. 31018061 and Above Condenser Mount, Serial No. 31018061 & Above	85804063	RD-3661*
	85812095	74R2536
	85812053	RD00179
Switch-Blower On/Off A/C High/Low Pressure, Drier Mount	9966238	04455
	518486	04456
	85804065	04525
<b>FORD/NEW HOLLAND 675D BACKHOE</b>		
Blower Motor Resistor, 3 Terminal  Resistor, 4 Terminal  Blower Motor Assembly	86010530	04437
	1255876C1 700710564	03242
	E5NN18N350AA E5NN18B310AA	03246
	E7NN18456AC	BA4011
Clutch Bearing-Sanden SD510	F0NN19D666AA	52560
Clutch-New Sanden SD510	F0NN19D649BA	8297
Compressor Shaft Seal Kit-Sanden SD510	F0NN19655AA	52552
Compressor-New Sanden SD510 New Sanden SD7H15, 5/01/1994 and Newer	F0NN19D629BA	9125AM
	85702706, 86511121	4673
Expansion Valve-Block Type	F1NN19849AA	EX03700
Receiver Drier	F1NN19959AA	21723
Switch-Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND 675E BACKHOE</b>		
Blower Motor-Assembly Resistor	85813079	73R5552
	85804041	03255
Clutch Bearing-Sanden SD7H15	85817172	52565
Clutch-New Sanden SD7H15	85817171	8445
Compressor Shaft Seal Kit	85817173	52554
Compressor-New Sanden SD7H15, Serial No. 31018061 and Above New Sanden SD7HB10, Serial No. 31011330 and Below	85812045	C009610
	85804059	7170AM
Condenser-Serial No. 31018061 and above	85812052	AC003345
Expansion Valve-Block Type	85804037	38892
Receiver Drier-Serial No. 31011330 and Below * Also needs 461-3126 Serial No. 31018061 and Above Condenser Mount, Serial No. 31018061 & Above	85804063	RD-3661*
	85812095	74R2536
	85812053	RD00179

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND 675E BACKHOE Cont.</b>		
Switch-Blower On/Off A/C High/Low Pressure, Drier Mount	9966238	04455
	518486	04456
	85804065	04525
<b>FORD/NEW HOLLAND 755A BACKHOE</b>		
Blower Motor-3/8" Double Shaft, 4 Wire Condenser Motor	E2NN18456AA	7231FHD
	E3NN19C634AA	BM-0368
Clutch-York, 6" Dia., 2 Groove, Standard Duty York, 6" Dia., 2 Groove, Heavy Duty	86529809	75R0452
	86529809	75R1202
Compressor Shaft Seal Kit-Tecumseh York	C9AZ19655B	20836
	C9AZ19655B	20986
Compressor-York, LH Suction, Rotolok York, RH Suction, Rotolok	N/A	7044
	N/A	7054
Expansion Valve	E3NN19849AA	38877
Switch-Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND 755B BACKHOE</b>		
Blower Motor-3/8" Double Shaft, 2 Wire Resistor, 3 Terminal  Resistor, 4 Terminal  Blower Motor, 3/8" Double Shaft, 4 Wire Condenser Motor	86010530	04437
	1255876C1 700710564	03242
	E5NN18N350AA E5NN18B310AA	03246
	E2NN18456AA	7231FHD
	E3NN19C634AA	BM-0368
	86529809	75R0452
Clutch-York, 6" Dia., 2 Groove, Standard Duty York, 6" Dia., 2 Groove, Heavy Duty	86529809	75R1202
	86529809	75R1202
Compressor Shaft Seal Kit-Tecumseh York	C9AZ19655B	20836
	C9AZ19655B	20986
Compressor-York, LH Suction, Rotolok York, RH Suction, Rotolok	N/A	7044
	N/A	7054
Expansion Valve	E3NN19849AA	38877
Switch-Blower	E9NN15122AA	71R1150
<b>FORD/NEW HOLLAND B95 BACKHOE</b>		
Blower Motor-Assembly Resistor	85813079	73R5552
	85804041	03255
Compressor-New Sanden SD7H15, 135mm, 1 Groove Clutch New Sanden SD7H15, 5 1/2", 2 Groove Clutch	87430122	CO095981
	85817170	CO09612
Receiver Drier-O'Ring	87315241	74R3066
Switch-High/Low Pressure	58504065	04525
<b>FORD/NEW HOLLAND LB75 BACKHOE</b>		
Blower Motor-Assembly Resistor	85813079	73R5552
	85804041	03255
Clutch Bearing-Sanden SD7H15	85817172	52565
Clutch-New sanden SD7H15	85817171	8445
Compressor Shaft Seal Kit	85817173	52554
Compressor-New Sanden SD7H15	85817170	C009612

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND LB75 BACKHOE Cont.</b>		
Condenser	85812052	AC003345
Expansion Valve-Block Type	85804037	38892
Receiver Drier-O'Ring	85826035, 85812095	74R2536
Condenser Mount	85812053	RD00179
Switch-Blower	9966238	04455
High/Low Pressure, Drier Mount	85804065	04525
<b>FORD/NEW HOLLAND LB90 BACKHOE</b>		
Blower Motor-Assembly	85813079	73R5552
Resistor	85804041	03255
Clutch Bearing-Sanden SD7H15	85817172	52565
Clutch-New Sanden SD7H15	85817171	8445
Compressor Shaft Seal Kit	85817173	52554
Compressor-New Sanden SD7H15	85812045	C009610
Condenser	85812052	AC003345
Expansion Valve-Block Type	85821130	21924
Receiver Drier	85826035 85812095	74R2536
Condenser Mount	85812053	RD00179
Switch-Blower	9966238	04455
High/Low Pressure, Drier Mount	85804065	04525
<b>FORD/NEW HOLLAND LB110 BACKHOE</b>		
Blower Motor-Assembly	85813079	73R5552
Resistor	85804041	03255
Clutch Bearing-Sanden SD7H15	85817172	52565
Clutch-New Sanden SD7H15	85817171	8445
Compressor Shaft Seal Kit	85817173	52554
Compressor-New Sanden SD7H15	85812045	C009610
Condenser	85812052	AC003345
Expansion Valve-Block Type	85821130	21924
Receiver Drier	85826035, 85812095	74R2536
Condenser Mount	85812053	RD00179
Switch-Blower	9966238	04455
High/Low Pressure, Drier Mount	85804065	04525
<b>FORD/NEW HOLLAND LB115 BACKHOE</b>		
Blower Motor-Assembly	85813079	73R5552
Resistor	85804041	03255
Clutch Bearing-Sanden SD7H15	85817172	52565
Clutch-New Sanden SD7H15	85817171	8445
Compressor Shaft Seal Kit	85817173	52554
Compressor-New Sanden SD7H15	85812045	C009610
Condenser	85812052	AC003345

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND LB115 BACKHOE Cont.</b>		
Expansion Valve-Block Type, 08/2000 and Older Block Type, 09/2000 and Newer	85804037	38892
	85821130	21924
Receiver Drier  Condenser Mount	85826035 85812095	74R2536
	85812053	RD00179
Switch-Blower  High/Low Pressure, Drier Mount	9966238	04455
	85804065	04525
<b>FORD/NEW HOLLAND C185 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
Compressor-New Sanden SD7H15	87026034	4664
Condenser	87546517, 87447385	AC003372
Evaporator-with Heater Core	87350424	EV903070
Receiver Drier-O'Ring	86625481	RD001116
Switch-High/Low Pressure	86625515	26507
<b>FORD/NEW HOLLAND C190 SKIDSTEER</b>		
Condenser	87546517, 87447385	AC003372
Compressor-New Sanden SD7H15	87026034	4664
Receiver Drier-O'Ring	86625481	RD001116
Switch-High/Low Pressure	86625515	26507
<b>FORD/NEW HOLLAND L175 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
Compressor-New Sanden SD5H11	87362509, 87546525	CO09397
Condenser	87546517	AC003392
Evaporator-with Heater Core	87350424	EV903070
Expansion Valve-Block Type	86639749	EX03700
Receiver Drier-O'Ring	86625481	RD001116
Switch-High/Low Pressure	86625515	26507
<b>FORD/NEW HOLLAND L185 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
Compressor-New Sanden SD7H15	87026034	4664
Condenser	87546517, 87447385	AC003372
Receiver Drier-O'Ring	86625481	RD001116
Switch-High/Low Pressure  Thermostat	86625515	26507
	86625480	26609
<b>FORD/NEW HOLLAND L190 SKIDSTEER</b>		
Compressor-New Sanden SD5H11  New Sanden SD7H15, Serial No. N8M459486 & Below	N/A	6361
	87026034	4664
Expansion Valve-Block Type	86639749	EX03700
Receiver Drier-O'Ring	86625481	RD001116



<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND LS140 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LS150 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LS160 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LS170 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LS180 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
Compressor-New Sanden SD7H15	87026034	4664
Receiver Drier-O'Ring	86625481	RD001116
Expansion Valve-Block Type	86639749	EX03700
<b>FORD/NEW HOLLAND LS180B SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
Receiver Drier-O'Ring, Metric Threads	86625481	RD001116
<b>FORD/NEW HOLLAND LS185B SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
Compressor-New Sanden SD7H15	87026034	4664
Receiver Drier-O'Ring, Metric Threads	86625481	RD001116
<b>FORD/NEW HOLLAND LS190 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
Receiver Drier-O'Ring, Metric Threads	86625481	RD001116
<b>FORD/NEW HOLLAND LS190B SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
Compressor-New Sanden SD7H15	87026034	4664
Receiver Drier-O'Ring, Metric Threads	86625481	RD001116
<b>FORD/NEW HOLLAND LX465 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LX485 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LX565 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LX665 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LX865 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LX885 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153
<b>FORD/NEW HOLLAND LX985 SKIDSTEER</b>		
Blower Motor Assembly	86592107	BA40153

<b>FORD/NEW HOLLAND CONSTRUCTION</b>	<b>OEM</b>	<b>PART #</b>
<b>FORD/NEW HOLLAND LM410 TELEHANDLER</b>		
Blower Motor Assembly	85824975	BA4005
Compressor-New Sanden SD7H15	98462948, 85812377	4646
Receiver Drier-O'Ring	85812680	20549
<b>FORD/NEW HOLLAND LM415 TELEHANDLER</b>		
Blower Motor Assembly	85824975	BA4005
<b>FORD/NEW HOLLAND LM420 TELEHANDLER</b>		
Blower Motor Assembly	85824975	BA4005
Compressor-New Sanden SD7H15	98462948, 85812377	4646
Receiver Drier-O'Ring	85812680	20549
<b>FORD/NEW HOLLAND LM425 TELEHANDLER</b>		
Compressor-New Sanden SD7H15	98462948, 85812377	4646
<b>FORD/NEW HOLLAND LM425A TELEHANDLER</b>		
Blower Motor Assembly	85824975	BA4005
Receiver Drier-O'Ring	85812680	20549
<b>FORD/NEW HOLLAND LM430 TELEHANDLER</b>		
Blower Motor Assembly	85824975	BA4005
Compressor-New Sanden SD7H15	98462948, 85812377	4646
Expansion Valve-Block Type	86639749	EX03700
Receiver Drier-O'Ring	85812680	20549
Switch-High-Low Pressure	85812697	26507
<b>FORD/NEW HOLLAND LM435 TELEHANDLER</b>		
Blower Motor Assembly	85824975	BA4005
Receiver Drier-O'Ring	85812680	20549
<b>FORD/NEW HOLLAND LM445 TELEHANDLER</b>		
Blower Motor Assembly	85824975	BA4005
<b>FORD/NEW HOLLAND LM5040 TELEHANDLER</b>		
Compressor-New Sanden SD7H15	87556183	CO09612
<b>FORD/NEW HOLLAND LM5060 TELEHANDLER</b>		
Compressor-New Sanden SD7H15	87556183	CO09612
Receiver Drier-O'Ring	87687070	20549
<b>FORD/NEW HOLLAND LM5080 TELEHANDLER</b>		
Compressor-New Sanden SD7H15	87556183	CO09612
<b>FORD/NEW HOLLAND LM630 TELEHANDLER</b>		
Compressor-New Sanden SD7H15	98462948, 85812377	4646
<b>FORD/NEW HOLLAND LM640 TELEHANDLER</b>		
Compressor-New Sanden SD7H15	98462948, 85812377	4646