

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK C70 TRACTOR</b>		
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
<b>MCCORMICK C80 TRACTOR</b>		
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
<b>MCCORMICK C85 TRACTOR</b>		
Compressor-Delphi SP10, 2 Groove Clutch	N/A	CO08810
Receiver Drier-O'Ring	N/A	RD1199
<b>MCCORMICK C90 TRACTOR</b>		
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
<b>MCCORMICK C100 TRACTOR</b>		
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
<b>MCCORMICK CX50 TRACTOR</b>		
Blower Motor-Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
Compressor-New Aftermarket Replacement for SD508, R-12  New Sanden SD7H15, R134A	1977959C1 97204C1	9571AM
	1999755C2/ C3	4609
Evaporator	251389A-1	EV902222
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
Switch-Blower Thermostat	168822C2 92101C1	71R1150 26300
<b>MCCORMICK CX60 TRACTOR</b>		
Blower Motor-Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
Compressor-New Aftermarket Replacement for SD508, R-12  New Sanden SD7H15, R134A	1977959C1 97204C1	9571AM
	1999755C2/ C3	4609
Evaporator	251389A-1	EV902222
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
Switch-Blower Thermostat	168822C2 92101C1	71R1150 26300

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK CX70 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Aftermarket Replacement for SD508, R-12  New Sanden SD7H15, R134A	1977959C1 97204C1	9571AM
	1999755C2	4609
<b>Evaporator</b>	251389A-1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2	71R1150
	92101C2	26300
<b>MCCORMICK CX75 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK CX80 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A-1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2	71R1150
	92101C2	26300
<b>MCCORMICK CX85 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	1999755C2/ C3	4609
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2	71R1150
	92101C2	26300

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK CX90 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A-1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2	71R1150
	92101C2	26300
<b>MCCORMICK CX95 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A-1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2	71R1150
	92101C2	26300
<b>MCCORMICK CX100 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Aftermarket Replacement for SD508, R-12  New Sanden SD7H15	1977959C1 97204C1	9571AM
	1999755C2/ C3	4609
<b>Evaporator</b>	251389A-1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat  Thermostat, Preset, Tier 3	168822C2	71R1150
	92101C2	26300
	6500235M1	26610
<b>MCCORMICK CX105 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	1999755C2/ C3	4609
<b>Evaporator</b>	251389A-1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK MC80 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2 92101C2	71R1150 26300
<b>MCCORMICK MC90 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2 92101C2	71R1150 26300
<b>MCCORMICK MC95 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2 92101C2	71R1150 26300
<b>MCCORMICK MC100 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	1999755C2	4609
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Blower Thermostat	168822C2 92101C2	71R1150 26300
<b>MCCORMICK MC105 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	1999755C2	4609
<b>Evaporator</b>	251389A1	EV902222

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK MC105 TRACTOR CONT.</b>		
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
Switch-Blower Thermostat	168822C2 92101C2	71R1150 26300
<b>MCCORMICK MC115 TRACTOR</b>		
Blower Motor-Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2 307153A1 359671A1	BA4021 03250
Compressor-New Sanden SD7H15	1999755C2	4609
Evaporator	251389A1	EV902222
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
Switch-Blower Thermostat	168822C2 92101C2	71R1150 26300
<b>MCCORMICK MC120 TRACTOR</b>		
Blower Motor-Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2 307153A1 359671A1	BA4021 03250
Evaporator	251389A1	EV902222
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
Switch-Blower Thermostat	168822C2 92101C2	71R1150 26300
<b>MCCORMICK MC135 TRACTOR</b>		
Blower Motor-Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2 307153A1 359671A1	BA4021 03250
Evaporator	251389A1	EV902222
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
Switch-Blower Thermostat	168822C2 92101C2	71R1150 26300
<b>MCCORMICK MTX110 TRACTOR</b>		
Blower Motor-Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2 307153A1 359671A1	BA4021 03250
Condenser	139870A1	AC002036
Evaporator	251389A1	EV902222
Expansion Valve	1990756C2 87033212	71R8330
Receiver Drier	1990758C2	26825
Switch-Thermostat	92101C2	26300

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK MTX120 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	709375A1	CO096394
<b>Condenser</b> Condenser, B Power, must Reuse Brackets	139870A1	AC002036
	708879A1	AC002050
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK MTX125 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	1999755C2	4609
<b>Condenser</b>	139870A1	AC002036
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK MTX135 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	709375A1	CO096394
<b>Condenser</b> Condenser, B Power, must Reuse Brackets	139870A1	AC002036
	708879A1	AC002050
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK MTX140 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	1999755C2	4609
<b>Condenser</b>	139870A1	AC002036
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK MTX150 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	709375A1	CO096394
<b>Condenser</b> Condenser, B Power, must Reuse Brackets	139870A1	AC002036
	708879A1	AC002050
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK MTX155 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Condenser</b>	139870A1	AC002036
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK MTX165 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	709375A1	CO096394
<b>Condenser</b> Condenser, must Reuse Brackets	139870A1	AC002036
	708879A1	AC002050
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK MTX175 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	1999755C2	4609
<b>Condenser</b>	139870A1	AC002036
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK MTX185 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	709375A1	CO096394
<b>Condenser</b> Condenser, must Reuse Brackets	139870A1	AC002036
	708879A1	AC002050
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK MTX200 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15 New Sanden SD7H15	1999755C2	4609
	709375A1	CO096394
<b>Condenser</b> Condenser, must Reuse Brackets	139870A1	AC002036
	708879A1	AC002050
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK XTX185 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Condenser</b> -must Reuse Brackets	708879A1	AC002050
<b>Compressor</b> -New Sanden SD7H15	710145A1	CO096395
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK XTX200 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15	710145A1	CO096395
<b>Condenser</b> -must Reuse Brackets	708879A1	AC002050
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300

<b>MCCORMICK - TRACTOR</b>	<b>OEM</b>	<b>PART #</b>
<b>MCCORMICK XTX215 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Compressor</b> -New Sanden SD7H15 New Sanden SD7H15	1999755C2	4609
	710145A1	CO0096395
<b>Condenser</b> -must Reuse Brackets	708879A1	AC002050
<b>Evaporator</b>	251389A1	EV902222
<b>Expansion Valve</b>	1990756C2 87033212	71R8330
<b>Receiver Drier</b>	1990758C2	26825
<b>Switch</b> -Thermostat	92101C2	26300
<b>MCCORMICK ZTX230 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A1	EV902222
<b>Receiver Drier</b>	1990758C2	26825
<b>MCCORMICK ZTX260 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A1	EV902222
<b>Receiver Drier</b>	1990758C2	26825
<b>MCCORMICK ZTX280 TRACTOR</b>		
<b>Blower Motor</b> -Blower Motor Assembly Blower Speed Resistor, 3 Terminal	178454A2	BA4021
	307153A1 359671A1	03250
<b>Evaporator</b>	251389A1	EV902222
<b>Receiver Drier</b>	1990758C2	26825