

MARK IV	OEM	Part #
MARK IV ROOFTOP		
Blower Motor -12 Volt Double Shaft 24 Volt Double Shaft	N/A	73R4102 73R4104
Condenser Motor -12 Volt 24 Volt	N/A	BM-0368 73R0504
Expansion Valve	20125	20359
Receiver Drier -Fieldmaster Fieldstar	21051	20507 20548